

# Oil Field Environmental Incident Summary

**Incident:** 20151125165151 **Date/Time of Notice:** 11/25/2015 16:51

**Responsible Party:** MARATHON OIL COMPANY

**Well Operator:** MARATHON OIL COMPANY

**Well Name:** BINGO 24-10TFH

**Field Name:** REUNION BAY

**Well File #:** 30682

**Date Incident:** 11/25/2015 **Time Incident:** 12:35

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 151

**Rng:** 93

**Sec:** 10

**Qtr:**

**Location Description:** On facility site

**Submitted By:** Callie Karrigan

**Received By:**

**Contact Person:** Bryson Goerres  
3172 HWY 22 N  
DICKINSON, ND 58601

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	25	Barrels	25	Barrels	25	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 12/9/2015

**Clean Up Concluded:** 11/25/2015

**Risk Evaluation:**

None

**Areal Extent:**

Release was on the facility

**Potential Environmental Impacts:**

Approximately 23 gallons went outside of containment onsite. There is minimal impact to the environment due to it still remaining onsite and being recovered immediately.

**Action Taken or Planned:**

Investigation to address the root cause as a valve failure or alignment. All valves were closed to stop release.

**Wastes Disposal Location:** Recovered fluids will be re-used on location. Any affected solids will be disposed of via Clean Harbors.

**Agencies Involved:** BIA, BLM

**Updates**

---

**Date:** 11/27/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a valve/piping connection leak, remained on the facility site according to the report. NDIC retains oversight.